



ALL ITEMS ARE FOR IMMEDIATE SHIPMENT. ALL SALES ARE FINAL.

<u>Qty</u>			<u>Item #</u>	<u>PUR</u> <u>Ticket#</u>	<u>Branch</u>	<u>Damage</u> <u>Description</u>	<u>Sell Price</u>	<u>Contact</u>	<u>Image Link</u>
<u>Fujitsu</u>									
1	AOUH24KWAH3	2 Ton Outdoor Unit	235510	S101659050	OTT	coil damage	\$1,900	Phil Wendland	Image Link
1	AOUH36KWAH4	36KBTU Multi Zone Outdoor Unit	235530	S101317871	WAT	No box	\$2,350.00	Brandon Wise	
1	AOUH36KPAS1	36KBTU Outdoor Unit	235598	S101754304	COL	dented opposite side of lineset connections	\$950.00	Tony Cochran	Image Link
<u>Grundfos</u>									
1	UPS40160F115v	96402782 Circulating Pump	36885	S101862729	WAT	Open Box, No damage	\$1,800	Brandon Wise	
<u>Reznor</u>									
1	UDXC75	75KBTU Unit Heater	178015	S101872696	DSM	Right bottom corner ding	\$1,000	Louis Miner	Image Link
<u>Ruud HVAC</u>									
1	RCFY6021STAAMC	5 Ton 21" Coil	215074	S101847323	OTT	Side damaged	\$550	Phil Wendland	Image Link
1	RH2TY3617STANNJ	3 Ton 17" Air Handler	230562	S101750381	SLK	Scratches on front door	\$1,000	Ryan Kerr	Image Link
1	RH2TY3617STANNJ	3 Ton 17" Air Handler	230562	S101788663	MSC	scratches near bottom	\$750	Ashley Aline	Image Link
<u>Ruud Water Heater</u>									
1	PROE151RUPOU	15G Electric Point of Use Water Heater	39599	S101842917	CDR	Top dented	\$325.00	Tim Troyna	Image Link
1	PROE28SRU95	28G Short Electric Water Heater	51809	S101800431	DSM	top & side dented	\$250.00	Louis Miner	Image Link
1	PROG4030NRH62MHDV	40G NG/LP Direct Vent Mfg Housing Water Heater	44781	S101765708	DSM	broken foot	\$550.00	Louis Miner	Image Link
1	PROG4030NRH62MHDV	40G NG/LP Direct Vent Mfg Housing Water Heater	44781	S101765927	DSM	broken foot	\$500.00	Louis Miner	Image Link
<u>Weatherking</u>									
1	TCFY6021STAAMC	5 Ton 21" Cased Coil	215061	S101793798	DSM	paint blemish	\$300.00	Louis Miner	Image Link
<u>Weil McClain</u>									
1	CGI6PIN	117-140KBTU NG/LP Induced Draft Boiler	35465	S101784188	MSC	right side dented	\$2,100.00	Ashley Aline	Image Link