

<u>Qty</u>		<u>Item #</u>	<u>Product Under Repair Ticket #</u>	<u>Branch</u>	<u>Damage Description if known</u>	<u>Sell Price</u>	
	<u>Ruud HVAC</u>						
1	RCF4824HTAMCA	171759	7409366	001-DM	top damaged	\$100.00	Image Link
1	RCF4824HTAMCA	171759	7409312	001-DM	side damaged	\$100.00	Image Link
1	U96VA0702317MSB	160837	7295629	007-SL	dented side	\$900.00	
1	U96VA0852521MSB	160838	7491580	001-DM	top and door damage	\$1,200.00	Image Link
	<u>Weatherking</u>						
1	WA1342AJ1NA	187601	7485772	018-DV	No box	\$500.00	
1	W95TC0401317M	230822	7509536	001-DM	Side dented	\$450.00	Image Link
1	WA1330BJ1NA	187599	See Kenny	207-WAS	bottom damaged	\$450.00	Image Link
	<u>Aspen</u>						
1	CC48D44245L1	110839	7480474	001-DM	dented on side	\$200.00	Image Link
	<u>Ruud Water Heater</u>						
1	PRO+G5040NRU67P	161302	7394115	001-DM	dented on bottom	\$100	Image Link
1	PRO+G75-76N	173845	7395861	210-COP	dented on top	\$110	Image Link
1	PRO+G75-76P	182860	7430448	001-DM	box damaged only	\$300	
1	G100-200	061993	7482099	001-DM	Side dented	\$4,200	Image Link
1	PROG50-38N	173857	7486907	007-SL	side damaged	\$250	Image Link
1	PROG40-38N	173855	7456422	007-SL	No box	\$500	
1	PROG5038NRU60	173857	7520458	001-DM	Dent near bottom	\$500	Image Link
1	ELD66-TB 4.5kw/4.5kw	286901	7493700	001-DM	dented near top	\$1,800	Image Link
	<u>Fujitsu</u>						
1	AOU24RLXFWH	189831	7498079	007-SL	No box	\$1,150.00	
	<u>AirEase</u>						
1	EC1P30AG-1	208912	7417043	220-COP	bottom damage	\$90.00	Image Link
	<u>Reznor</u>						
1	UDX 60	287599	7508802	001-DM	dent on top	\$550.00	Image Link
	<u>Moen</u>						
1	S1311ORB	186120	See Josh	206-JCB	small dent	\$200.00	Image Link
	<u>Sterling</u>						
1	93140-0	276476	7396212	001-DM	gouge in finish	\$100	Image Link

ALL ITEMS ARE FOR IMMEDIATE SHIPMENT-ALL SALES ARE FINAL