

<u>Qty</u>			<u>Item #</u>	<u>PUR Ticket#</u>	<u>Branch</u>	<u>Damage Description if known</u>	<u>Sell Price</u>		
	<u>Fujitsu</u>								
1	AOUG12LMAS1	1 Ton outdoor unit	272540	7444337	001-DM	Fin Damage	\$500		
1	AMUG24LMAS	2 Ton Air Handler	277940	8257913	201-ROL	Front cabinet damage	\$1,100	Image Link	
	<u>Lifebreath</u>								
1	RNC-155	RNC 155 HRV	188379	8027285	001-DM	Scrape on side	\$525		
	<u>Reznor</u>								
1	UDX 75	75KBTU Unit Heater	287600	8223538	001-DM	Damaged See Reid	\$750		
1	UDX100	100KBTU Unit Heater	287601	7925534	001-DM	Bottom dented	\$750		
1	UDX 75	75KBTU Unit Heater	287600	7946529	001-DM	Minor Damage- Ask for Earl	\$750		
	<u>Ruud Water Heater</u>								
1	PROG7576RNU	75G NG Water Heater	173845	8194058	001-DM	Dented	\$1,000		
2	PROG40-38N RU 62	40G NG Water Heater	173855	8227163	011-MU	Dented Lower right side (both units)	\$475	Image Link	
1	PROG50-36P RU62	50G LP Water Heater	173842	8225532	001-DM	Damaged-Ask for Earl	\$600		
1	PROG40S-36P RU62	40G Short LP Water Heater	161296	8225492	001-DM	Damaged-Ask for Earl	\$550		
1	GHE100SU-200	100G 199KBTU Comm Water Heater	246484	8225115	001-DM	No box 2 small creases	\$7,800		
1	PROE40M2RU95	40G Electric Water Heater	175634	8025479	001-DM	Box damaged	\$500		
1	PROE50-T2-RU95	50G Electric Water Heater	176309	8205136	001-DM	Top damaged	\$300		
1	PROG50-38N RU60	50G NG Water Heater	173857	8206210	001-DM	no box	\$550		
	<u>Ruud HVAC</u>								
1	RCF4824HTAMCA	4 Ton 24" Coil	171759	8087276	001-DM	Box damaged	\$650		
1	RCF6024STAMCA	5 Ton 24" Coil	171754	8253492	007-SL	Cabinet damage	\$500	Image Link	
1	U96VA0702317MSB	96% 70KBTU ECM Multi Position Furn	160837	8225666	001-DM	Slightly dented	\$1,500		
1	RCF6024STAMCA	5 Ton 24" Coil	171754	8079271	001-DM	Forklift dent on side	\$600		
1	U96VA082521MSB	96% 85KBTU ECM Multi Position Furn	160838	8230156	007-SL	Major damage side and bottom	\$1,100	Image Link	
1	U96VA082521MSB	96% 85KBTU ECM Multi Position Furn	160838	8230141	007-SL	Side damaged	\$1,400	Image Link	
1	U96VA082521MSB	96% 85KBTU ECM Multi Position Furn	160838	8230132	007-SL	Left side multiple dents	\$1,400	Image Link	
1	R95TC1151524M	95% 115KBTU Multi Position Furnace	222229	8209779	002-OT	Damaged Front Mid & Bottom	\$900	Image Link	
	<u>Weatherking</u>								
1	WP1448AJ1NA	4 Ton Heat Pump	187619	8201417	001-DM	no box	\$1,200		
1	TCF2414STAMCA	2 Ton 14" Cased Coil	187626	8260097	018-DV	Cabinet damage	\$250	Image Link	
1	WA1324AJ1NA	2 Ton Condenser	187598	8258140	018-DV	Top Damage	\$500	Image Link	
	<u>Weil McLain</u>								
1	Ultra 105 S4	105KBTU NG/LP Boiler	237965	8225358	001-DM	Damaged-Ask for Earl	\$2,500		
1	CGA-5-PIDN	117KBTU NG Boiler	113283	7613062	001-DM	Damaged-Ask for Earl	\$1,700		
1	EVG 220	179KBTU NG/LP Boiler	179790	7775488	001-DM	Damaged-Ask for Earl	\$4,200		
	<u>MTI</u>								
1	QPLUS551	QPLUS551 Kembry Soaking Tub	272570	8246353	001-DM	scratch on front of tub	\$1,500		

ALL ITEMS ARE FOR IMMEDIATE SHIPMENT-ALL SALES ARE FINAL