



<u>Qty</u>			<u>Item #</u>	<u>PUR Ticket#</u>	<u>Branch</u>	<u>Damage Description</u>	<u>Sell Price</u>	<u>Contact</u>	<u>Image Link</u>
<u>GE</u>									
1	JGS760SPSS	Gas slide in range	104869	S101411664	COL	Side damaged	1400	Tony Cochran	Image Link
<u>REZNOR</u>									
1	UXDC-100	100Kbtu Unit Heater	178017	S101398687	DSM	minor louver damage	\$950	Louis Miner	Image Link
<u>RUUD HVAC</u>									
1	R951T1005A21M4SNAS	95+% 100KBTU	124493	S101410957	DSM	top scratch side dent	\$1,800	Bill Truman	Image Link
<u>RUUD WATER HEATER</u>									
1	PROG5036PRU62	50G Tall LP Water Heater	44753	S101414886	MTN	top dented	\$800.00	Brent Bjelland	Image Link
1	PROE38S2RU95	38G Short Electric Water Heater	44794	S101378709	OSB	top/side dented	\$350.00	Charley Johnson	Image Link
1	PROE36S2RU95	36G Short Electric Water Heater	51803	S101363636	JFC	Side/top dented	\$200.00	Kent Robinson	Image Link
<u>WEATHERKING</u>									
1	WHIT4824STANJA	4 Ton R410 Air Handler	104367	S101379724	DSM	Dented lower back side and side	\$550	Louis Miner	Image Link