



SCRATCH & DENT

ALL ITEMS ARE FOR IMMEDIATE SHIPMENT. ALL SALES ARE FINAL.

<u>Qty</u>	<u>Item #</u>	<u>PUR Ticket#</u>	<u>Branch</u>	<u>Damage Description</u>	<u>Sell Price</u>	<u>Contact</u>	<u>Image Link</u>
Allied							
1	KGB060S4EB	5 Ton 70KBTU Package Unit	118424	S101423559	OSB	coil pushed in, no leaks	\$1,200 Charley Johnson Image Link
Fujitsu							
1	ACUH18LUAS1	18KBTU Indoor Unit	116827	S101537452	DSM	Wrong box, no damage	\$900 Louis Miner
Reznor							
1	UDXC-75	75KBTU Unit Heater	178015	S101537722	DSM	scratch on bottom	\$800 Louis Miner Image Link
1	UDXC-75	75KBTU Unit Heater	178015	S101533721	DSM	Minor dent on bottom	\$700 Joe Schiltz Image Link
1	UDXC-125	125KBTU Unit Heater	178019	S101534532	DSM	Fins scratched & bent	\$700 Joe Schiltz Image Link
Ruud HVAC							
1	RH2TY6024STANNJ	5 Ton 24" Air Handler	230599	S101536584	DSM	side dented	\$1,500 Louis Miner Image Link
1	RCFY2417STANMC	2 Ton 17" Cased Coil	207771	S101514910	DSM	Scratched, small dent	\$200 Joe Schiltz Image Link
1	RD16AY36AJVCA	3 Ton 16 Seer Condenser	262578	S101504906	DSM	forkleft dent on side	\$1,250 Louis Miner Image Link
1	RH2TY4821STANNJ	4 Ton 2 Stage 21" Air Handler	230574	S101509580	DSM	side damaged	\$850 Louis Miner Image Link
Ruud Water Heater							
1	PRO+G7576NRU	75G NG Tall Water Heater	44756	S101480539	DAV	side damaged	\$700 Steve Weitz Image Link
1	PROE40T2RU95	40G Tall Electric Water Heater	46226	S101514002	DSM	dented near top	\$200 Joe Schiltz Image Link
1	PROG4036PRU67PV	40G LP Power Vent Water Heater	39283	S101523768	JFC	side damaged near bottom	\$750 Kent Robinson Image Link
Weatherking							
1	W962W0855A21M4SBAS	96% 85kbtu 2 Stage 21" Multi Pos furnace	128369	S101499879	DSM	Bottom of cabinet damaged	\$1,150 Louis Miner Image Link
1	W951T1155A24M4SNAS	95% 115kbtu 24" Multi Pos furnace	125021	S101543664	MSC	Top damaged	\$1,000 Rachel Beller Image Link