



ALL ITEMS ARE FOR IMMEDIATE SHIPMENT. ALL SALES ARE FINAL.

<u>Qty</u>	<u>Item #</u>	<u>PUR Ticket#</u>	<u>Branch</u>	<u>Damage Description</u>	<u>Sell Price</u>	<u>Contact</u>	<u>Image Link</u>
Allied							
1	KGB060S4EB	5 Ton 70KBTU Package Unit	118424	S101423559	OSB	coil pushed in, no leaks	\$1,000 Charley Johnson Image Link
Fujitsu							
1	ACUH18LUAS1	18KBTU Indoor Unit	116827	S101537452	DSM	Wrong box, no damage	\$800 Louis Miner Image Link
Reznor							
1	UDXC-125	125KBTU Unit Heater	178019	S101534532	DSM	Fins scratched & bent	\$550 Joe Schiltz Image Link
Ruud HVAC							
1	RH2TY6024STANNJ	5 Ton 24" Air Handler	230599	S101536584	DSM	side dented	\$1,100 Louis Miner Image Link
Ruud Water Heater							
1	PROE50T2RU95	50G Tall Electric Water Heater	46225	S101560088	SLK	side dented	\$600.00 Ryan Kerr Image Link
1	PROE50T2RU95	50G Tall Electric Water Heater	46225	S101569861	COL	small dent	\$600.00 Tony Cochran Image Link
1	PROG40S36PRU62	40G LP Short Water Heater	39302	S101570110	MTN	side dented	\$700.00 Ricky Glenn Image Link
1	PROG4038NRU62	40G NG Tall Water Heater	44766	S101558835	MUS	big dent on side	\$550.00 Chase Brown Image Link
Weatherking							
1	W951T0703A17M4SNAS	95% 70kbtu 1 Stage 17" Multi Pos Furnace	125017	S101567916	SLK	Top back and corners dented	\$1,000.00 Ryan Kerr Image Link
1	W962W0855A21M4SBAS	96% 85kbtu 2 Stage 21" Multi Pos furnace	128369	S101499879	DSM	Bottom of cabinet damaged	\$900.00 Louis Miner Image Link