



ALL ITEMS ARE FOR IMMEDIATE SHIPMENT. ALL SALES ARE FINAL.

<u>Qty</u>			<u>Item #</u>	<u>PUR Ticket#</u>	<u>Branch</u>	<u>Damage Description</u>	<u>Sell Price</u>	<u>Contact</u>	<u>Image Link</u>
<b><u>Fujitsu</u></b>									
1	ACUH18LUAS1	<b>LAST CALL</b> 18KBTU Indoor Unit	116827	S101537452	DSM	Wrong box, no damage	\$200	Louis Miner	
<b><u>Navien</u></b>									
1	NPE240S2	199KBTU NG/LP Tankless Water Heater	110171	S101697224	DSM	Damaged mounting bracket	\$1,050	Louis Miner	<a href="#">Image Link</a>
<b><u>Ruud HVAC</u></b>									
1	RH2TY4821STANNJ	4 Ton 2 Stage 21" Air Handler	230574	S101509580	DSM	Bottom damaged	\$950	Louis Miner	<a href="#">Image Link</a>
1	U98MV0855A21UPSGAP	98% 85KBTU 21" Mod Upflow Furnace	124510	S101622676	DSM	No box, no damage	\$1,900	Louis Miner	
<b><u>Ruud Water Heater</u></b>									
1	PROE40T2RU95	40G Tall Electric Water Heater	46226	S101711335	DSM	Top dented, dent in side	\$550.00	Louis Miner	<a href="#">Image Link</a>
1	PROG2932NRU63	29G Tall NG Water Heater	44763	S101556859	SLK	Small dent on top & bottom	\$500.00	Robert Edwards	<a href="#">Image Link</a>
1	PROE40T2RU95	40G Tall Electric Water Heater	46226	S101684217	DSM	damaged rear, top & bottom	\$350.00	Louis Miner	<a href="#">Image Link</a>
1	PROE40T2RU95	40G Tall Electric Water Heater	46226	S101693879	DSM	top & side dents	\$350.00	Louis Miner	<a href="#">Image Link</a>
1	PRO50T2RU95	50G Tall Electric Water Heater	46225	S101672768	DAV	top damaged	\$450.00	Steve Weitz	<a href="#">Image Link</a>
1	PROG5042NRU67PV	50G NG Power Vent Water Heater	39282	S101142165	DUB	No box, side dented	\$850.00	Josh Jankowski	<a href="#">Image Link</a>
1	PROG5042NRU67PV	50G NG Power Vent Water Heater	39282	S101643229	WAU	No box, no damage	\$1,150.00	Eric Clark	
1	PROE38S2RU95B	40G Short Electric Water Heater	44794	S101635047	COL	Side dented	\$200.00	Tony Cochran	<a href="#">Image Link</a>
<b><u>Weatherking</u></b>									
1	TCFY6024STANMC	5 Ton 24" Cased Coil	215063	S1016820807	CDR	dented middle both sides	\$750.00	Amy Schoonover	<a href="#">Image Link</a>
1	W801T0754A17UHSNAS	80% 75KBTU 17" Upf/Hz Furnace	124999	S101693395	DAV	No box, no damage	\$650.00	Steve Weitz	
1	W951T0705A21M4SNAS	95% 70KBTU 21" Multi Pos Furnace	125018	S101693688	DAV	Front damaged on left side	\$650.00	Steve Weitz	<a href="#">Image Link</a>