



ALL ITEMS ARE FOR IMMEDIATE SHIPMENT. ALL SALES ARE FINAL.

| <u>Qty</u>               |                    |                                                         | <u>Item #</u> | <u>PUR</u><br><u>Ticket#</u> | <u>Branch</u> | <u>Damage</u><br><u>Description</u> | <u>Sell Price</u> | <u>Contact</u> | <u>Image Link</u>          |
|--------------------------|--------------------|---------------------------------------------------------|---------------|------------------------------|---------------|-------------------------------------|-------------------|----------------|----------------------------|
| <u>Fujitsu</u>           |                    |                                                         |               |                              |               |                                     |                   |                |                            |
| 1                        | ACUH18LUAS1        | <b>**LAST CALL**</b><br>18KBTU Indoor Unit              | 116827        | S101537452                   | DSM           | Wrong box, no damage                | \$200             | Louis Miner    |                            |
| <u>Ruud HVAC</u>         |                    |                                                         |               |                              |               |                                     |                   |                |                            |
| 1                        | RH2TY4821STANNJ    | 4 Ton 2 Stage 21" Air Handler                           | 230574        | S101509580                   | DSM           | Bottom damaged                      | \$800             | Louis Miner    | <a href="#">Image Link</a> |
| 1                        | U98MV0855A21UPSGAP | 98% 85KBTU 21" Mod Upflow Furnace                       | 124510        | S101622676                   | DSM           | No box, no damage                   | \$1,800           | Louis Miner    |                            |
| <u>Ruud Water Heater</u> |                    |                                                         |               |                              |               |                                     |                   |                |                            |
| 1                        | PROE40T2RU95       | 40G Tall Electric Water Heater                          | 466226        | S101716698                   | COL           | dent on top edge                    | \$600.00          | Tony Cochran   | <a href="#">Image Link</a> |
| 1                        | PROE40T2RU95       | 40G Tall Electric Water Heater                          | 46226         | S101716699                   | COL           | dented on bottom corner             | \$600.00          | Tony Cochran   | <a href="#">Image Link</a> |
| 1                        | PROE40T2RU95       | 40G Tall Electric Water Heater                          | 46226         | S101711335                   | DSM           | Top dented, dent in side            | \$500.00          | Louis Miner    | <a href="#">Image Link</a> |
| 1                        | PROG2932NRU63      | 29G Tall NG Water Heater                                | 44763         | S101556859                   | SLK           | Small dent on top & bottom          | \$400.00          | Robert Edwards | <a href="#">Image Link</a> |
| 1                        | PROE40T2RU95       | 40G Tall Electric Water Heater                          | 46226         | S101684217                   | DSM           | damaged rear, top & bottom          | \$300.00          | Louis Miner    | <a href="#">Image Link</a> |
| 1                        | PRO50T2RU95        | 50G Tall Electric Water Heater                          | 46225         | S101672768                   | DAV           | top damaged                         | \$350.00          | Steve Weitz    | <a href="#">Image Link</a> |
| 1                        | PROG5042NRU67PV    | 50G NG Power Vent Water Heater                          | 39282         | S101142165                   | DUB           | No box, side dented                 | \$750.00          | Josh Jankowski | <a href="#">Image Link</a> |
| 1                        | PROG5042NRU67PV    | 50G NG Power Vent Water Heater                          | 39282         | S101643229                   | WAU           | No box, no damage                   | \$1,000.00        | Eric Clark     |                            |
| 1                        | PROE38S2RU95B      | <b>**LAST CALL**</b><br>40G Short Electric Water Heater | 44794         | S101635047                   | COL           | Side dented                         | \$150.00          | Tony Cochran   | <a href="#">Image Link</a> |
| <u>Weatherking</u>       |                    |                                                         |               |                              |               |                                     |                   |                |                            |
| 1                        | TCFY6024STANMC     | 5 Ton 24" Cased Coil                                    | 215063        | S101682807                   | CDR           | dented middle both sides            | \$650.00          | Amy Schoonover | <a href="#">Image Link</a> |
| 1                        | W801T0754A17UHSNAS | 80% 75KBTU 17" Upf/Hz Furnace                           | 124999        | S101693395                   | DAV           | No box, no damage                   | \$600.00          | Steve Weitz    |                            |
| 1                        | W951T0705A21M4SNAS | 95% 70KBTU 21" Multi Pos Furnace                        | 125018        | S101693688                   | DAV           | Front damaged on left side          | \$550.00          | Steve Weitz    | <a href="#">Image Link</a> |