



Qty			Item #	PUR Ticket#	Branch	Damage Description	Sell Price	Contact	Image Link
Fujitsu									
1	AOUH36KWAH4	36KBTU Multi Zone Outdoor Unit	235530	S101317871	WAT	No box	\$3,000.00	Brandon Wise	
1	AOUH36KPAS1	36KBTU Outdoor Unit	235598	S101754304	COL	dented opposite side of lineset connections	\$1,500.00	Tony Cochran	Image Link
Ruud HVAC									
1	RH2TY3617STANNJ	3 Ton 17" Air Handler	230562	S101788663	MSC	scratches near bottom	\$1,600	Ashley Aline	Image Link
1	RCFZ6021STAAM	5 Ton 21" Cased Coil	215074	S101750272	DSM	side damaged	\$300	Louis Miner	Image Link
Ruud Water Heater									
1	PROE50T2RU95	50G Tall Electric Water Heater	46225	S101793994	DSM	side puncture	\$550.00	Louis Miner	Image Link
1	PROE28SRU95	28G Short Electric Water Heater	51809	S101800431	DSM	top & side dented	\$600.00	Louis Miner	Image Link
1	PROE50T2RU95	50G Tall Electric Water Heater	46225	S101783554	DSM	scratches & small dents	\$500.00	Joe Schiltz	Image Link
1	PROG40S38NRU62	40G NG Short Water Heater	45075	S101759773	MTN	side damaged	\$350.00	Brent Bjelland	Image Link
1	PROG40S38NRU62	40G NG Short Water Heater	45075	S101759361	MTN	side damaged	\$450.00	Brent Bjelland	Image Link
1	PROG4030NRH62MHDV	40G NG/LP Direct Vent Mfg Housing Water Heater	44781	S101765708	DSM	broken foot	\$1,050.00	Louis Miner	Image Link
1	PROG4030NRH62MHDV	40G NG/LP Direct Vent Mfg Housing Water Heater	44781	S101765927	DSM	broken foot	\$1,050.00	Louis Miner	Image Link
1	PROG5038NRU60	50G NG Tall Water Heater	44767	S101679724	MUS	top damaged	\$300.00	Harmon Miller	Image Link
1	PROE38S2RU93SB	38G Short Electric Water Heater	216520	S101727878	DSM	small dent and drag marks on bottom	\$300.00	Louis Miner	Image Link
Weatherking									
1	TCFY6021STAAMC	5 Ton 21" Cased Coil	215061	S101793798	DSM	paint blemish	\$750.00	Louis Miner	Image Link
1	WA13NY24AJ1NA	2 Ton 13SEER Condenser	209332	S101796846	DSM	corner dented	\$900.00	Louis Miner	Image Link
1	TCFY3621STANMC	3 Ton 21" Cased Coil	215056	S101782393	DSM	front dented	\$400.00	Joe Schiltz	Image Link
1	TCF3617STAMCA	**LAST CALL** 3 Ton 17" Cased Coil	53261	S101757253	DSM	Small dent front lower left side	\$100.00	Louis Miner	Image Link
1	TCFY6024STANMC	5 Ton 24" Cased Coil	215063	S101682807	CDR	dented middle both sides	\$150.00	Amy Schoonover	Image Link
Weil McClain									
1	CGI6PIN	117-140KBTU NG/LP Induced Draft Boiler	35465	S101784188	MSC	right side dented	\$3,000.00	Ashley Aline	Image Link
Copper Tube									
60'	2CKS60	2" K Soft Copper	41486	S101803718	DSM	small dents muddy no box	\$2,600.00	Louis Miner	Image Link