

<u>Qty</u>			<u>Item #</u>	<u>PUR Ticket#</u>	<u>Branch</u>	<u>Damage Description</u>	<u>Sell Price</u>	<u>Contact</u>	
	<u>Fujitsu</u>								
1	AOUH12KZAH1	12KBTU Outdoor Unit	235246	S101051535	MSC	dent lower left side	1000	Staci Gray	Image Link
1	AOUG09LZAS1	9KBTU Outdoor Unit	96813	S101059080	DSM	Minor fin damage	650	Joe Schlitz	Image Link
1	AOUH24KPAS1	24KBTU Outdoor Unit	235595	S101034805	DSM	Small dent & scratches	\$650	Louis Miner	Image Link
	<u>Ruud HVAC</u>								
1	TCFZ4821STANMC	4 Ton 21" Cased Coil	125466	S101047790	DAV	Dented upper right side	\$425	Steve Weitz	Image Link
1	TCFZ6024STANMC	5 Ton 24" Cased Coil	125469	S101062494	COL	Side pushed in	\$500	Tony Cochran	Image Link
1	R962V0703A17M	96%+ 70KBTU 2 Stage Multi Pos Furnace	124498		DSM	dent lower right side	1700	Louis Miner	Image Link
	<u>Ruud Water Heater</u>								
1	GHE100SU-160A	100G Comm NG Water Heater	79645		WAR	side dents	\$8,300.00	Matt Vesecky	Image Link
1	PROG5038NRU60	50G NGWater Heater	44767	S101030783	COL	lower side damage	\$500.00	Tony Cochran	Image Link
1	PROG40-40 RU67PV	40G NG Power Vent Water Heater	39281	S100985641	DSM	Top/Side dented	\$500.00	Joe Schlitz	Image Link
	<u>Weatherking</u>								
1	W951T0403A17M4SNAS	95% 40KBTU 1 Stage Frunace	125015	S101029982	DAV	left side dented	\$600.00	Nathan Lauritzen	Image Link
	<u>Weil McClain</u>								
1	AQUA PLUS 85	Indirect Water Heater	32739	S100939384	DSM	No Box	\$1,000	Joe Schlitz	

ALL ITEMS ARE FOR IMMEDIATE SHIPMENT-ALL SALES ARE FINAL