

<u>Qty</u>			<u>Item #</u>	<u>PUR Ticket#</u>	<u>Branch</u>	<u>Damage Description</u>	<u>Sell Price</u>	<u>Contact</u>	
<u>Fujitsu</u>									
1	AOUH12KZAH1	12KBTU Outdoor Unit	235246	S101051535	MSC	dent lower left side	\$700	Staci Gray	Image Link
1	AOUG09LZAS1	9KBTU Outdoor Unit	96813	S101059080	DSM	Minor fin damage	\$450	Joe Schlitz	Image Link
<u>Ruud HVAC</u>									
1	R962V0855A21M4SCAP	96%+ 85KBTU 2 Stage Multi Pos Furnace	124500	S101079225	DSM	Top & side dented	\$1,700	Joe Schiltz	Image Link
1	TCFZ4821STANMC	4 Ton 21" Cased Coil	125466	S101047790	DAV	Dented upper right side	\$250	Steve Weitz	Image Link
1	TCFZ6024STANMC	5 Ton 24" Cased Coil	125469	S101062494	COL	Side pushed in	\$300	Tony Cochran	Image Link
1	R962V0703A17M	96%+ 70KBTU 2 Stage Multi Pos Furnace	124498	DSM	DSM	dent lower right side	\$1,400	Louis Miner	Image Link
<u>Ruud Water Heater</u>									
1	PRO40T2RU95	40G Electric Water Heater	46226	S101071015	DSM	bottom damage	\$350.00	Joe Schiltz	Image Link
1	GHE100SU-160A	100G Comm NG Water Heater	79645	WAR	WAR	side dents	\$7,900.00	Matt Vesecky	Image Link
1	PROG5038NRU60	50G NGWater Heater	44767	S101030783	COL	lower side damage	\$300.00	Tony Cochran	Image Link
<u>Weatherking</u>									
1	W951T0403A17M4SNAS	95% 40KBTU 1 Stage Furnace	125015	S101029982	DAV	left side dented	\$400.00	Nathan Lauritzen	Image Link

ALL ITEMS ARE FOR IMMEDIATE SHIPMENT-ALL SALES ARE FINAL