

<u>Qty</u>			<u>Item #</u>	<u>PUR Ticket#</u>	<u>Branch</u>	<u>Damage Description</u>	<u>Sell Price</u>	<u>Contact</u>	
	<u>Allied</u>								
1	25M03 7AH1AE30PX	2.5 Ton Air Handler	237269	S101110998	WAR	side damage	\$900	Jennifer Todd	Image Link
	<u>Elkay</u>								
1	LZS8WLSP	EZH20 Station	47051	S101072074	DSM	No box	\$1,550	Joe Schiltz	
	<u>Fujitsu</u>								
1	AOUH18KZAH1	18KBTU Outdoor Unit	235523	S101100134	DSM	minor fin damage and a small dent on top	\$1,150	Louis Miner	Image Link
1	AOUH12KZAH1	12KBTU Outdoor Unit	235246	S101051535	MSC	dent lower left side	\$425	Staci Gray	Image Link
1	AOUG09LZAS1	9KBTU Outdoor Unit	96813	S101059080	DSM	Minor fin damage	\$275	Joe Schlitz	Image Link
	<u>Ruud HVAC</u>								
1	R962V0855A21M4SCAP	96%+ 85KBTU 2 Stage Multi Pos Furnace	124500	S101079225	DSM	Top & side dented	\$1,350	Joe Schiltz	Image Link
1	TCFZ6024STANMC	5 Ton 24" Cased Coil	125469	S101062494	COL	Side pushed in	\$100	Tony Cochran	Image Link
1	R962V0703A17M	96%+ 70KBTU 2 Stage Multi Pos Furnace	124498		DSM	dent lower right side	\$1,200	Louis Miner	Image Link
	<u>Ruud Water Heater</u>								
1	PROG40S38NRU62	40G NG Short Water Heater	45075	S101122315	DSM	small dents on backside	\$700.00	Louis Miner	Image Link
1	PROE50T2RU95	50G Electric Water Heater	46225	S101121410	OSB	side/top dented	\$500.00	Charley Johnson	Image Link
1	PRO+G75-76N RU PV	75G NG Power Vent Water Heater	44759	S100912600	SLK	top dented	\$1,700.00	Ryan Kerr	Image Link
1	PROE50T2RU95	50G Electric Water Heater	46225	S101093138	ROL	multiple dents & damage	\$500.00	Eli Clark	Image Link
1	GHE100SU-160A	100G Comm NG Water Heater	79645		WAR	side dents	\$7,500.00	Matt Vesecky	Image Link
1	PROG5038NRU60	50G NG Water Heater	44767	S101030783	COL	lower side damage	\$150.00	Tony Cochran	Image Link

ALL ITEMS ARE FOR IMMEDIATE SHIPMENT-ALL SALES ARE FINAL