



ALL ITEMS ARE FOR IMMEDIATE SHIPMENT. ALL SALES ARE FINAL.

Qty			Item #	PUR Ticket#	Branch	Damage Description	Sell Price	Contact	Image Link
<u>Fujiitsu</u>									
1	AOUH36KWAH4	36KBTU Multi Zone Outdoor Unit	235530	S101317871	WAT	No box	\$2,800.00	Brandon Wise	
1	AOUH36KPAS1	36KBTU Outdoor Unit	235598	S101754304	COL	dented opposite side of lineset connections	\$1,350.00	Tony Cochran	Image Link
<u>Ruud HVAC</u>									
1	RH2TY3617STANNJ	3 Ton 17" Air Handler	230562	S1017503891	SLK	Scratches on front door	\$1,600	Ryan Kerr	Image Link
1	RH2TY3617STANNJ	3 Ton 17" Air Handler	230562	S101788663	MSC	scratches near bottom	\$1,300	Ashley Aline	Image Link
<u>Ruud Water Heater</u>									
1	PROE40T2RU95	40G Tall Electric Water Heater	46226	S101812469	SLK	Side damaged near top & bottom	\$350.00	Nute Williams	Image Link
1	PROE28SRU95	28G Short Electric Water Heater	51809	S101800431	DSM	top & side dented	\$400.00	Louis Miner	Image Link
1	PROG40S38NRU62	40G NG Short Water Heater	45075	S101759773	MTN	side damaged	\$250.00	Brent Bjelland	Image Link
1	PROG4030NRH62MHDV	40G NG/LP Direct Vent Mfg Housing Water Heater	44781	S101765708	DSM	broken foot	\$900.00	Louis Miner	Image Link
1	PROG4030NRH62MHDV	40G NG/LP Direct Vent Mfg Housing Water Heater	44781	S101765927	DSM	broken foot	\$850.00	Louis Miner	Image Link
1	PROE38S2RU93SB	38G Short Electric Water Heater	216520	S101727878	DSM	small dent and drag marks on bottom	\$150.00	Louis Miner	Image Link
<u>Weatherking</u>									
1	W951T0855A21M4SNAS	95% 85KBTU 21" Multi Pos Furnace	125019	S101813387	JFC	Front damaged	\$850.00	Kent Robinson	Image Link
1	TCFY6021STAAMC	5 Ton 21" Cased Coil	215061	S101793798	DSM	paint blemish	\$550.00	Louis Miner	Image Link
1	TCFY3621STANMC	3 Ton 21" Cased Coil	215056	S101782393	DSM	front dented	\$250.00	Joe Schiltz	Image Link
<u>Weil McClain</u>									
1	CGI6PIN	117-140KBTU NG/LP Induced Draft Boiler	35465	S101784188	MSC	right side dented	\$2,750.00	Ashley Aline	Image Link
<u>Copper Tube</u>									
60'	2CKS60	2" K Soft Copper	41486	S101803718	DSM	small dents muddy no box	\$2,200.00	Louis Miner	Image Link