

<u>Qty</u>			<u>Item #</u>	<u>PUR Ticket#</u>	<u>Branch</u>	<u>Damage Description if known</u>	<u>Sell Price</u>		
<u>Fujitsu</u>									
1	ASU24RLF	2 Ton Indoor Unit	28971	S100303368	COL	Casing damaged and warped	\$250.00	Last call	Image Link
1	AOU36RLXFZ1	3 Ton Outdoor Unit	44724	See Charley	OSB	Front panel and bottom damaged	\$1,000.00		Image Link
1	AOU18RLXFWH	1-1/2 Ton Outdoor Unit	54507	S100231811	DSM	Side damaged	\$200.00	Last call	Image Link
1	AOUH36LMAH1	3 Ton Outdoor Unit	132154	S100162825	DSM	Side dented	\$1,000.00		Image Link
<u>Ruud HVAC</u>									
1	RA14AZ36AJ1NA	3 Ton 14 Seer Condenser	123594	S100267625	DSM	Fin damage	\$1,200.00		Image Link
<u>Weatherking</u>									
1	WA13NZ24AJ1NA	2 Ton 13 Seer Condenser	124943	S100256061	DAV	Sides dented	\$500.00		Image Link
<u>Reznor</u>									
1	UDX 125	125KBTU Unit Heater NG	109784	S100176462	DSM	Scratch & Dent lower front	\$600.00		Image Link
1	UDX 175	175KBTU Unit Heater NG	109786	S100153816	DSM	Lower front damaged	\$300.00		Image Link
<u>Ruud Water Heater</u>									
1	PROG4036PRU67PV	40G LP Power Vent Water Heater	39283	S100304573	WAU	Small dent by burner cover	\$1,300		
1	PROG3032NRH63-MH	30G NG/LP Manf Home Water Heater	44783	S100280700	DSM	No Box	\$700		
1	G100-200	100G 199KBTU Comm Water Heater	13042	S100193508	DSM	Lots O' Dents & Scratches	\$5,800		Image Link
1	GHE100SU200	100G 199KBTU Comm Water Heater	76415	S100183540	DSM	Side Dented	\$4,600		Image Link

ALL ITEMS ARE FOR IMMEDIATE SHIPMENT-ALL SALES ARE FINAL