



ALL ITEMS ARE FOR IMMEDIATE SHIPMENT. ALL SALES ARE FINAL.

Qty			Item #	PUR Ticket#	Branch	Damage Description	Sell Price	Contact	
Navien									
1	NPF700-060U3BH	60kbtu Hydro Furnace	171372	S101241015	DSM	dents & scratches multiple sides	\$1,350	Joe Schiltz	Image Link
Ruud HVAC									
1	R951T0703A17M4SNAS	95% 75kbtu Multi Pos Furnace	124490	S101274850	OTT	Left side damage	\$1,300	Phil Wendland	Image Link
1	R951T0603A17M4SNAS	95% 60kbtu Multi Pos Furnace	124489		WAT	damaged top rear left corner	\$750	Brandon Wise	Image Link
1	R951T0403A17M4SNAS	95% 40kbtu Multi Pos Furnace	124488		WAT	Damaged bottom/back/both sides	\$400	Brandon Wise	Image Link
1	RCFZ6021STAAMC	5 Ton Cased Coil	123680		WAT	dented back corner right side & front	\$150	Brandon Wise	Image Link
1	RH2TY6024STANNJ	5 Ton Two Stage Air Handler	230599	S101190496	DSM	Bottom dented	\$450	Joe Schiltz	Image Link
Ruud Water Heater									
1	PROG40S38NRU62	40G NG Short Water Heater	45075	S101270010	MSC	small dent near bottom	\$750.00	Rachel Beller	Image Link
1	PROG40S36NRU67PV	40G NG Power Vent Water Heater	39284	S101267584	SLK	small dent bottom left side	\$1,300.00	Nute Williams	Image Link
1	PROG4036PRU62	40G LP Water Heater	46364	S101248991	WAT	small scratches & dents on side	\$500.00	Brandon Wise	Image Link
1	PROG5036PRU62	50G LP Water Heater	44753	S101234564	DSM	Dent near bottom	\$400.00	Louis Miner	Image Link
1	GHE100SU-160A	100G Comm NG Water Heater	79645		WAR	side dents	\$4,500.00	Matt Vesecky	Image Link
Schwank									
1	JT-BS18-AN	180K Burner	114395	S100737963	DSM	Scratches & dents	\$50.00	Joe Schiltz	
Weatherking									
1	W951T0703A17M4SNAS	95% 70kbtu	125017		WAT	partial right side return cut	\$500.00	Brandon Wise	Image Link
1	W951T0603A17M4SNAS	95% 60kbtu Multi Pos Furnace	125016		WAT	upper right side & top side dented	\$500.00	Brandon Wise	Image Link
1	WH1PY2417STANNJ	2 Ton Air Handler	215163	S101200363	DSM	scuff right rear and blower assy	\$75.00	Joe Schiltz	Image Link