



SCRATCH & DENT

ALL ITEMS ARE FOR IMMEDIATE SHIPMENT. ALL SALES ARE FINAL.

Qty	Item #		PUR Ticket#	Branch	Damage Description	Sell Price	Contact	Image Link
Allied								
1	ABCE7S48MA4X50	4 Ton Commercial Air Handler	84783	S100583315	MOB	minor dent on side	\$750	Jerry Hartgrove Image Link
1	KGB060S4EB	5 Ton 70kbtu Package Unit	118424	S101423559	OSB	coil pushed in, no leaks	\$2,300	Charley Johnson Image Link
Aspen								
1	CC36B3J210L101	3 Ton cased coil	246869	S101427539	OTT	bottom corner dented	\$100	Phil Wendland Image Link
Fujitsu								
1	AOU15KZAH1	15kbtu Outdoor Unit	235210	S101437140	COL	ousing bent near service valv	\$450	Tony Cochran Image Link
1	AOU15KZAH1	15kbtu Outdoor Unit	235210	S101437113	COL	unit dropped side damage	\$300	Tony Cochran Image Link
Ruud HVAC								
1	RH1PY4821STANNJ	4 Ton 21" Air Handler	240356	S101479595	DSM	No box, undamaged	\$1,450	Louis Miner box is covered in drywall splatter
1	R92V0855A21M4SCAP	96% 85Kbtu Multi Pos Furnace	124500	S101473786	DSM	mall dent slight wobble to un	\$2,000	Louis Miner Image Link
1	RA14AT24AJ1NA	2 Ton 14 Seer Condenser	215110	S101471391	DSM	shroud damage	\$1,400	Louis Miner Image Link
1	R802V1005A21UHSCAP	9% 100kbtu upflow/horz Furna	127288	S101471291	DSM	minor dent lower left side	\$1,500	Louis Miner Image Link
Ruud Water Heater								
1	PROE50T2RU95	50G Tall Electric Water Heater	46225	S101482309	COL	Top & side dented	\$625.00	Tony Cochran Image Link
1	PROE201RUPOU	Electric Point of Use Water He	39601	S101477487	JFC	Top dented	\$425.00	Kent Robinson Image Link
1	PROE40T2RU95	40G Tall Electric Water Heater	46225	S101459785	JFC	dented side	\$300.00	Kent Robinson Image Link
1	PROE101RUPOU	Electric Point of Use Water He	39589	S101424380	DSM	side dented	\$300.00	Joe Schiltz Image Link
1	PROE40T2RU95	40G Tall Electric Water Heater	46226	S101449625	DSM	side dented	\$300.00	Louis Miner Image Link